

Incident Summary Report II-663369-2018 (6287) (Final)

SUPPORTING INFORMATION	Incident Date	March 12, 2018	
	Location	Burnaby	
	Regulated industry sector	Escalator	
	Impact Injury	Qty injuries	0
		Injury description	No injuries
		Injury rating	None
	Damage	Damage description	4 damaged steps, step axial, upper comb plates, up thrust track, hold down track, upper landing plate and stressed step chain.
		Damage rating	Major
Incident rating	Major		
Incident overview	Escalator steps misaligned and came into contact with the upper landing comb plates, causing a pile up. This is a malfunction that occurs when the moving components come into contact with the stationary components		
INVESTIGATION CONCLUSIONS	Site, system and components	Inside an escalator, a pair of chains wraps around two pairs of gears that are driven by an electric motor. The motor and step chain sit within a metal structure known as the truss, which extend between the floors served by the escalator. Within the truss, the escalator houses steps and tracks. At the top of the unit the steps and track are kept aligned by upthrust tracks and hold down tracks. This allows the conveyer like rotation to travel through the truss with precise alignment	
	Failure scenario(s)	<p>Licensed contractor failed to provide field mechanics with specifications and tolerances for the Otis 506 escalators.</p> <p>Upthrust track was not set to the correct specification which allowed the step rollers to ride higher or out of alignment prior to entering into the upper combplates.</p> <p>The hold down track was not set to correct specifications, which allowed the step to rise more than 1mm. The ability for the step to rise lead to the step and track to come into contact.</p>	
	Facts and evidence	<p>Onsite investigation observations:</p> <ul style="list-style-type: none"> The proper adjustment for the upthrust track is 1mm. This escalator the upthrust track was set to 6mm. (5mm above maximum allowance) The hold down track was allowing the steps to rise 4mm. (3mm above maximum allowance) 	

Incident Summary Report II-663369-2018 (6287) (Final)

	<ul style="list-style-type: none">• Through conversation the Field Mechanic made the Safety Officer aware that he did not have the upthrust track specifications for allowances. Field Mechanic was not provided the documentation to maintain those specifications.• Field Mechanic was not trained or checking for these allowances.
Causes and contributing factors	<p>It is highly probable that the cause of this pile up was that The upthrust track and hold down track were not set to proper specifications.</p> <p>A contributing factor was that the Field mechanic(s) were not aware of the specifications of the upthrust track and the hold down track when doing regular inspections and clean downs of the internal components of the escalator.</p>


Photos or diagrams (if necessary)




Steps piled up into upper combplates.



Example of a properly adjusted upthrust track, showing the correct clearance.



Upthrust track as found. This is showing the clearance beyond 1mm.



Step hold down track and step up lift tab.

This helps keep the step in alignment as it rotates in the upper end. Proper setting of 1mm clearance being shown here. During incident it was found at 4mm.